















# Selection guide - Section G

## Industrial controls

							
<b>Series</b>	<b>A1</b>	<b>A01</b>	<b>A01</b>	<b>A01</b>	<b>A01</b>	<b>A01ES</b>	<b>A01</b>
<b>Type</b>	Pushbutton	Pushbutton	Indicator	Rotary	Keylock	Emergency Stop	Mushroom Head Pushbutton
<b>Page</b>	<b>G-4</b>	<b>G-5</b>	<b>G-6</b>	<b>G-7</b>	<b>G-8</b>	<b>G-9</b>	<b>G-11</b>
<b>Poles</b>	1,2,3,4	1,2,3,4		1,2,3,4	1,2,3,4	1,2	1,2,3,4
<b>Sealing</b>	IP65	IP65	IP65	IP65	IP65	IP65	IP65
<b>Back panel sealing</b>	Option	Option	Option	Option	Option	Option	Option
<b>Illuminated</b>	Yes	Yes	Yes	No	No	No	No
<b>Maximum ratings</b>	6A 250VAC 6A 12VDC	6A 250VAC 6A 12VDC	N/A	6A 250VAC 6A 12VDC	6A 250VAC 6A 12VDC	1,5A 250VAC AC-15	6A 250VAC 6A 12VDC
<b>Panel cut-out</b>							
Ø16mm		X	X	X	X	X	X
Ø22mm	X	X	X	X	X		X
<b>Flush mounting</b>	Yes	Option	Option	Option	Option	No	Option
<b>Terminal options</b>							
Solder lugs	X	X	X	X	X	X	X
Quick-connect	X	X	X	X	X	X	X
PCB Mounting	Option	Option	Option	Option	Option	Option	Option
							
<b>Series</b>	<b>A02</b>	<b>A02</b>	<b>A02</b>	<b>A02ES</b>	<b>A02</b>	<b>A03</b>	<b>ES</b>
<b>Type</b>	Pushbutton	Indicator	Rotary / Keylock	Emergency Stop	Mushroom Head Pushbutton	Pushbutton	Emergency Stop
<b>Page</b>	<b>G-15</b>	<b>G-18</b>	<b>G-19 - G-20</b>	<b>G-21</b>	<b>G-22</b>	<b>G-24</b>	<b>G-25</b>
<b>Poles</b>	1,2,3,4,n		1,2,3,4,n	1,2	1,2,3,4	1,2,3,4	2,3
<b>Sealing</b>	IP65	IP65	IP65	IP65	IP65	IP65	IP65,IP67,IP69K
<b>Back panel sealing</b>	No	No	No	No	No	Option	No
<b>Illuminated</b>	Yes	Yes	No	No	No	Yes	No
<b>Maximum ratings</b>	16A 250VAC 12A 12VDC	16A 250VAC 12A 12VDC	16A 250VAC 12A 12VDC	2,5A 380VAC AC-15	16A 250VAC 12A 12VDC	6A 250VAC 6A 12VDC	1A 24VDC
<b>Panel cut-out</b>							
Ø22mm	X	X	X	X	X	X	X
Ø30mm	X	X	X			X	Ø 28mm
<b>Flush mounting</b>	Yes	Yes	Option	No	Option	Yes	No
<b>Terminal options</b>							
Solder lugs						X	X
Quick-connect	Option	Option	Option	Option	Option	X	
Screw	X	X	X	X	X		
Straight PC							X
PCB Mounting	No	No	No	No	No	Option	No